

DH-PFA109

Mount Adapter



- Aluminum alloy material
- Matched with particular cameras, beautiful and elegant designed








Scene

Suitable for camera mounting with operating temperature from -40° C to $+60^{\circ}$ C (-40° F to $+140^{\circ}$ F) and relative humidity less than 90%.


Technical Specification		
Model	DH-PFA109	
Material	Aluminum alloy	
Dimensions	134.1 mm \times 134.1 mm \times 83.5 mm (5.28" \times 5.28" \times 3.29") (L \times W \times H)	
Weight	0.3 kg (0.66 lb)	
Load Bearing	1.0 kg (2.2 lb)	
Operating Temperature	-40°C to +60°C (-40°F to +140°F)	
Operating Humidity	<90% (RH)	
Color	White	
Applicable Camera	Please see "Accessory Selection"	

Ordering Information		
Туре	Model	Description
Camera Mount	DH-PFA109	Mount Adapter

Installation



Dimensions (mm[inch])



Rev 001.001